First check for the Lithium switch. In the ON position the converter will output 14.4- 14.6 VDC single stage for LiFePO4 batteries.



The converter replacement section PD4135CSV, will have the above switch.

If you do not have the switch check for $\,$ This 4 wire harness .





Disconnect it and place a .1 spacing jumper over the 2 pins as shown.





We can send a jumper with your address.